ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 11 | Kuvempu Nagar |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0620 | 3rd Crs | Kalathur layout |
| **Segment No.** | **Total Length (m)** | |
| 11/S-W0620/S120323 | 127.17 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 127.17 | 77.546878 | 13.059283 | 77.545719 | 13.059108 | RI-S56 | DEAD END |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION | 960000 | 2011 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2011 - 2012 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION | 011-12-000008 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/E-TND/193/2011-12 | 02/11/2011 | 90 |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 02/11/2011 | 01/11/2012 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| NATARAJ.R | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9880095123 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | Ranganath |
| **Date of Inspection** | **Remarks** | |
| 25/03/2016 | completed | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition |  | This photo seems out of range. |
| Road Condition |  | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | SIDDIAH GOWDA | 28/03/2016 | 24/04/2016 | completed |
| SE | SRINIVAS REDDY | 28/03/2016 | 24/04/2016 | COMPLETED |
| EE | SRINIVAS REDDY | 28/03/2016 | 24/04/2016 | COMPLETED |
| AEE | PRAKESH | 25/03/2016 | 24/04/2016 | COMPLETED |
| AE | RANGANATH | 25/03/2016 | 24/04/2016 | COMPLETED |
| AE | RANGANATH | 25/03/2016 | 24/04/2016 | COMPLETED |

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 11 | Kuvempu Nagar |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0636 | 7th Crs | Kalathur layout |
| **Segment No.** | **Total Length (m)** | |
| 11/S-W0636/S120904 | 97.85 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 97.85 | 77.545845 | 13.058819 | 77.546735 | 13.058968 | RI-S56 | W0709 |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION | 960000 | 2011 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2011 - 2012 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION | 011-12-000008 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/E-TND/193/2011-12 | 02/11/2011 | 90 |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 02/11/2011 | 01/11/2012 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| NATARAJ.R | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9880095123 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | Ranganath |
| **Date of Inspection** | **Remarks** | |
| 25/03/2016 | completed | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | SIDDIAH GOWDA | 28/03/2016 | 24/04/2016 | completed |

| | | | | |
|---|---|---|---|---|
| SE | SRINIVAS REDDY | 28/03/2016 | 24/04/2016 | COMPLETED |
| EE | SRINIVAS REDDY | 28/03/2016 | 24/04/2016 | COMPLETED |
| AEE | PRAKESH | 25/03/2016 | 24/04/2016 | COMPLETED |
| AE | RANGANATH | 25/03/2016 | 24/04/2016 | COMPLETED |
| AE | RANGANATH | 25/03/2016 | 24/04/2016 | COMPLETED |